

FITNESS CERTIFICATE

To be filed by the Inspecting Officer (Asst. Engineer)
(Re: G.O. Ms. 20/70/ PWD DL 23 - 01 - 1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

ASHA.K.S.
S.N.S. SAMAJAM VIDYAMANDIR
EDAMUTTAM, CHAVAKKAD, VALAPAD

GF - 5 class rooms, 1 Toilet Block
Stair room, Verandah, 335.30m².
FF - 5 class rooms, 1 Toilet Block
Stair room, Verandah, 335.30m².
TOTAL - 670.60m².

2019 - 2020.

5. Period for which the certificate is issued
6. Nature of defects, if any
 - a) Foundation and basement
 - b) Superstructure
 - c) Doors and Windows
 - d) Wood work wrought and put up
 - e) Roof
 - f) Flooring
 - g) Miscellaneous (Cracks, etc.)
7. Any major defects noticed which will render the building unsafe in any manner

NIL
NIL
NIL
NIL
NIL
NIL
NIL
NIL


8. Whether maintenance works have been done properly
9. Whether the structure is sound or not for conducting classes

YES -
The structure is found to be sound for conducting classes under normal weather conditions

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.


CERTIFICATE

certified that the school building was inspected by me on 30/8/2019 and found to be fit / unfit to conduct classes, for the period 2019 - 2020. for the reasons stated above.

SUGUNA. P. K. 
Principal
SNS Samajam Vidyamandir,
Edamuttam

Place VALAPAD
Date: 30/8/2019.




MANAGER
S.N.S. Samajam Vidya Mandir
Edamuttam


ASHA.K.S.
Assistant Engineer
LSGD Section
Valapad Grama Panchayath